## SECTION 1.0 EXECUTIVE SUMMARY

Environmental Connection, Inc., (EC) was contracted by Richard Stockton University (Stockton) of Galloway, New Jersey to perform an asbestos containing material inspection of the buildings located on the main and satellite campuses throughout the University system.

SECTION 3.0 ASBESTOS SAMPLING RESULe (O)-9.6N9tYme4

## 3.02 Observatory

| Table 2 - Analytical Results Summary<br>Stockton University<br>Observatory – Building 6A | | | |
|---|---|---|---|
| ID # | Material | PLM Results | TEM Results |
| 01 | Drywall | None Detected | N/A |
| 01A | Joint Compound | None Detected | N/A |
| 02 | 12” x 12” Gray Floor Tile (No Glue) | None Detected | None Detected |
| 03 | Door Caulk | None Detected | None Detected |

N/A – Not Applicable

## 3.08 Generator/Fire Pump/HSG Storage

| Table 8 - Analytical Results Summary<br>Stockton University<br>Generator / Fire Pump / HSG Storage - Building 35 | | | |
|---|---|---|---|
| ID # | Material | PLM Results | TEM Results |
| 01 | Paste Sealant on Fiberglass Insulation | None Detected | None Detected |
| 02 | Drywall | None Detected | N/A |
| 02A | Joint Compound | None Detected | N/A |
| 03 | Saddle Insulation | None Detected | N/A |
| 04 | Grey Vinyl Cove Baseboard | None Detected | None Detected |
| 04A | Glue assoc. with Grey Vinyl Cove Baseboard | None Detected | None Detected |
| 05 | Interior Boiler Materials | Assumed | |

## 3.10 Student Housing III

| Table 10- Analytical Results Summary<br>Stockton University<br>Student Housing III - Building 37 | | | |
|---|---|---|---|
| ID # | Material | PLM Results | TEM Results |
| 01 | Textured Finish on Concrete Ceiling Deck | None Detected | N/A |
| 02 | Carpet Glue | None Detected | None Detected |
| 03<br>03A | Drywall | None Detected | N/A |

## 3.15 Unified Science Center

| Table 15- Analytical Results Summary<br>Stockton University<br>Unified Science Center- Building 51 | | | |
|---|---|---|---|
| ID # | Material | PLM Results | TEM Results |
| 01 | Spray on Fireproofing | None Detected | N/A |
| 02 | 12" x 12" White and Tan Marble Floor Tile | None Detected | None Detected |
| 02A | Glue assoc. with White and Tan Floor Tile | None Detected | None Detected |

## 3.16 Housing IV Commons

| Table 16- Analytical Results Summary<br>Stockton University<br>Housing IV Commons- Building 80 | | | |
|---|---|---|---|
| ID # | Material | PLM Results | TEM Results |
| 01 | Sheetrock | None Detected | N/A |
| 01A | Joint Compound | None Detected | N/A |
| 02 | Stucco | None Detected | N/A |
| 03 | Sheetrock | Assumed | |
| 03A | Joint Compound | Assumed | |
| 04 | Ceramic Tile Wet Bed | Assumed | |
| 05 | Tan Cove Base | Assumed | |
| 05A | Glue associated with Tan Cove Base | Assumed | |
| 06 | Paste associated with Fiberglass | Assumed | |
| 07 | Window/Door Caulk | Assumed | |
| 08 | Expansion Caulk | Assumed | |

## 3.17 Housing IV Building 81

| Table 17- Analytical Results Summary<br>Stockton University<br>Housing IV Apartments - Building 81 | | | |
|---|---|---|---|
| ID # | Material | PLM Results | TEM Results Detected |
| 01 | 12” x 12” Beige and Tan Marble Floor Tile | None Detected | None Detected |
| 01A | Glue assoc. with Beige and Tan Marble Floor Tile | - | None Detected |
| 02 | Tan Vinyl Cove Base | None Detected | None Detected |

## 3.26 Housing V Ivy Hall

| Table 26- Analytical Results Summary<br>Stockton University<br>Housing V-Ivy Hall - Building 120 | | | |
|---|---|---|---|
| ID # | Material | PLM Results | TEM Results |
| 01 | Sheetrock | None Detected | N/A |
| 01A | Joint Compound | None Detected | N/A |
| 02 | Gray Cove Base | Assumed | |
| 02A | Glue associated with Gray Cove Base | Assumed | |
| 03 | Carpet Glue | Assumed | |
| 04 | Ceramic Tile Wet Bed | Assumed | |
| 05 | 2' x 4' Cubed Ceiling Tile | None Detected | N/A |
| 06 | Wood Floor Underlay | Assumed | |
| 07 | Plumbers Paste | Assumed | |
| 08 | Dark Gray Sheet Flooring | Assumed | |
| 08A | Glue associated with Dark Gray Sheet Flooring | Assumed | |
| 09 | Light Gray Sheet Flooring | Assumed | |
| 09A | Glue associated with Light Gray Sheet Flooring | Assumed | |
| 10 | Sink Undercoat | Assumed | |
| 11 | Stair Tread Glue | Assumed | |

## 3.27 Housing V Juniper Hall

| Table 27- Analytical Results Summary<br>Stockton University<br>Housing V-Juniper Hall - Building 121 | | | |
|---|---|---|---|
| ID # | Material | PLM Results | TEM Results |
| 01 | Sheetrock | None Detected | N/A |
| 01A | Joint Compound | None Detected | N/A |
| 02 | Light Gray Cove Base | Assumed | |
| 02A | Glue associated with Light Gray Cove Base | Assumed | |
| 03 | Carpet Glue | Assumed | |
| 04 | Ceramic Tile Wet Bed | Assumed | |
| 05 | 2' x 4' Cubed Ceiling Tile | None Detected | N/A |
| 06 | Wood Floor Vapor Barrier | Assumed | |
| 07 | Plumbers Paste | Assumed | |
| 08 | Dark Gray Sheet Flooring | Assumed | |
| 08A | Glue associated with Dark Gray Sheet Flooring | Assumed | |
| 09 | Light Gray Sheet Flooring | Assumed | |
| 09A | Glue associated with Light Gray Sheet Flooring | Assumed | |
| 10 | | | |

## 3.28 Housing V Kerria Hall

| Table 28- Analytical Results Summary<br>Stockton University<br>Housing V-Kerria Hall - Building 122 | | | |
|---|---|---|---|
| ID # | Material | PLM Results | TEM Results |
| 01 | Sheetrock | None Detected | N/A |
| 01A | Joint Compound | None Detected | N/A |
| 02 | | | |

## 3.31 Housing V Nectar Hall

Table 31- Ana 9 -0 0 9.96 261.72 28 0.72 oTj EMC ET /Artifact <</MCID

## 3.35 Kramer Hall

| Table 35- Analytical Results Summary<br>Stockton University<br>Kramer Hall -Hammonton - Building 2526 | | | |
|---|---|---|---|
| ID # | Material | PLM Results | TEM Results |
| 01 | 12” x 12” Black and White Stone Floor Tile | Assumed | |
| 01A | Glue associated with 12”x 12” Black and White Floor T | Assumed | |
| 02 | 2’ x 4’ Suspended Ceiling Tile with Indents | None Detected | N/A |
| 03 | | | |

Analysis revealed that five (5) of the materials sampled contain greater than 1% asbestos content by weight. Analysis also revealed three (3) materials that contain trace amounts of asbestos content. The analytical results were integrated into the Asbestos Inventory/Management Plan. The Management Plan provides historical documentation of confirmed, assumed, and asbestos containing materials throughout the campus. The location, approximate quantity, and condition of each confirmed and assumed asbestos containing material was documented during the inspection and can also be found in the Management Plan. Trace asbestos containing materials are not governed by USEPA regulations. As such, the location, quantity, and condition of these materials was not recorded during the inspection.

## SECTION 4.0 DAMAGE ASSESSMENT

The location and condition of damaged confirmed and assumed asbestos containing materials was recorded in the Asbestos Inventory/Management Plan.

co-5.51149 e-19pa11(a73 Td62.3 ( )10.9 )10.9 (oe.00

Fiber Release Episode Records- Fiber release episode or potential fiber release episode reports are to be placed in this section.

Bulk Sampling Records- Bulk sampling reports, which include a summary of the work,
-1 oa-1 e4-1.7 ( )--4.on(-1 )-gu(-1 )-6 ( o) dTw -10.-1.141(ep)1(r)3(,C57ul)-6.6 (k)10g (or)-33.(4

- Maintain an Asbestos Inventory Management Plan for the facility
- Consult the Management Plan prior to all renovation activities.
- Should any previously unidentified suspect materials be discovered during renovation activities, all work should cease until the materials are sampled by an accredited asbestos building inspector.
- Employ a USEPA accredited Asbestos Project Designer to develop Plans and Specifications for any planned asbestos abatement projects
- Utilize a New Jersey Department of Labor licensed Asbestos Contractor to abate asbestos containing materials to facilitate planned renovation activities in accordance with federal and New Jersey requirements for asbestos abatement in public buildings
- Perform air monitoring in accordance with federal and New Jersey requirements for asbestos abatement in public buildings. EC recommends daily air monitoring during abatement activities in addition to clearance air monitoring at the completion of abatement.

Should you have any questions or require additional information, please contact the undersigned at your convenience.

Respectfully Submitted:
ENVIRONMENTAL CONNECTION, INC.

Jordan Reed
Project Manager